

OCTOBER 28, 2024

T-Mobile Park

Presentation to the
Washington State Ballpark
Public Facilities District (PFD)
on the
2024 Annual Inspection

T-Mobile Park
1250 1st Ave S.
Seattle, WA 98134

Thomas Duffy, PE
Principal

Thornton Tomasetti



Reach

Our Locations

5 Continents

1200 Engineers, Architects and Professionals
38 Offices
Projects in 54 Countries



MAJOR STADIUM EXPERIENCE

MLB Ballparks

Angel Stadium of Anaheim, Anaheim, CA

AT&T Park, San Francisco, CA

Chase Field*, Inspection & Maint., Phoenix, AZ

Kauffman Stadium Renovations, Kansas City, MO

Marlins Park* Peer Review & Insp, Miami, FL

Miller Park* Analysis & Roof Rehab, Milwaukee, WI

Nationals Park, Washington, DC

PETCO Park, San Diego, CA

PNC Park, Pittsburgh, PA

Safeco Field* Analysis and Roof Rehab, Seattle, WA

U.S. Cellular Field, Chicago, IL

Wrigley Field Renovations, Chicago, IL

Yankee Stadium, Bronx, NY

*** Significant movable element**

NFL Stadiums

The Adaptive Reuse of Soldier Field, Chicago, IL

Ford Field, Detroit MI

Georgia Dome, Atlanta, GA

Lambeau Field, South End Zone and North End Zone Expansions, Green Bay, WI

Lincoln Financial Field, Renovation, Philadelphia, PA

LP Field, Nashville, TN

Mercedes-Benz Stadium*, Review and Support, Atlanta, GA

Mercedes-Benz Superdome, Enhancements 2009-2011, New Orleans, LA

MetLife Stadium, East Rutherford, NJ

Hard Rock (Dolphins) Stadium, Miami, FL

State Farm (Univ. of Phx) Stadium*, Annual Serv, Phoenix, AZ



U.S. Bank Stadium*, Minneapolis, MN

2024 INSPECTION SCOPE:

1. Bowl & Garage
2. Retractable Roof (and supporting structure)
3. Mechanization System
4. Spot Cleaning & Painting Program
5. Data Assessment



BOWL AND GARAGE



BOWL AND GARAGE

Designation Tier	Slab Edge Length (ft)	Total Slab Edge Percentage (%)
0	11,540	59.9
1	1,388	7.2
2	276	1.4
3	1,348	7.0
4	4,614	24.0
5	95	0.5
Total	19,262	100

Table 1. Tier Designation of Damage or Deterioration

Designation Tier	Description of Damage or Deterioration	Repair Procedure
0 Intact	≤ 1/16" gap between bent plate and concrete slab edge	No actions required
1 Superficial	≤ 1/4" gap between bent plate and concrete slab edge	Remove organics and inject gap with epoxy
2 Low	> 1/4" gap between bent plate and concrete slab edge	Tier 1 repair + additional expansion anchors required to close gap
3 Moderate	≤ 1/4" gap between bent plate and concrete slab edge + long-term debris	Wire brush and grind out debris and inject gap with epoxy
4 High	> 1/4" gap between bent plate and concrete slab edge + long-term debris	Tier 3 repair + additional expansion anchors required to close gap
5 Critical	Significant damage to bent <u>plate</u> or concrete spalling through railing anchors	Remove damaged bent plate and spalled concrete ; replace in-kind with expansion anchors and inject gap with epoxy

BOWL AND GARAGE



20240730_155843 (Page C-4)



20240730_141935 (Page C-17)



20240730_095328 (Page C-39)

Figure 19. Photos of Representative Slab Edge Conditions Categorized Tier 1

BOWL AND GARAGE



20240730_151624 (Page E-12)



20240730_114319 (Page E-31)



20240730_102030 (Page E-48)

Figure 21. Photos of Representative Slab Edge Conditions Categorized Tier 3


BOWL AND GARAGE



20240730_143434 (Page G-3)



20240730_131859 (Page G-7)



20240730_103327 (Page G-11)

Figure 23. Photos of Representative Slab Edge Conditions Categorized Tier 5

RETRACTABLE ROOF AND SUPPORTING STRUCTURE AND SUPPORTING STRUCTURE




Figure 1: 2024 roof inspection scope.

RETRACTABLE ROOF AND SUPPORTING STRUCTURE



RETRACTABLE ROOF AND SUPPORTING STRUCTURE





RETRACTABLE ROOF AND SUPPORTING STRUCTURE



RETRACTABLE ROOF AND SUPPORTING STRUCTURE



RETRACTABLE ROOF AND SUPPORTING STRUCTURE



ROOF MECHANIZATION SYSTEM (MECHANICAL AND ELECTRICAL)

2.6.3 Motors

The insulation of the existing DC motor system were tested using a Megohmmeter. The testing was performed with a Fluke 1520 meter set to the 250 Volt setting. A ten-second sample duration was used.

Location	Armature [MΩ]	Field [MΩ]	Date	Comment
P1 N	11.59	2.489	3/20/2024	
P1 S	1.022	3.259	3/20/2024	
P2 NE	8.06	28	3/19/2024	
P2 NW	1.469	39.92	3/19/2024	
P2 SE	1.513	0.033	3/19/2024	Test performed prior to two motor replacements: 2SEEC2 on 3/20/2024; 2SEEC1 on 3/21/2024
P2 SW	6.15	6.34	3/19/2024	
P3 N	45.4	1.764	3/20/2024	
P3 S	21.67	2.347	3/19/2024	

The field readings for Panel 2 Southeast were observed to be low. Additionally, the overload circuit on motor 2SEEC1 was tripped. Further investigation of individual motors and gearboxes found:

- Motor 2SEEC1 had failed insulation and was indicating a direct short
- Motor 2SEWC2 had water intrusion into the top junction box as well as into the motor casing.

Based on these findings, TT recommended both motors be replaced. Mariners staff replaced both motors with spares the following day.

ROOF MECHANIZATION SYSTEM (MECHANICAL AND ELECTRICAL)

ROOF MECHANIZATION SYSTEM (MECHANICAL AND ELECTRICAL)

WHEEL BEARINGS

Panel 2 South Wheel Bearings Investigation




Over-worn, overloaded bearing. Dark grey grease. G5 wear



Worn bearing. Purple/brown grease. G4 wear



Normally-worn bearing. Purple. G3 wear



Brand new grease after 1 run. Mixed with residual grey grease. Purple G1-2 wear.



Brand new grease. Bright red. G1 wear

- Color scaling from G5 (bad) to G1 (good).
- After investigating several wheel bearings on Panel 2 South, various grease colors have been found indicating different amounts of wear.

GREASE REPLACEMENT

